

Nº	CODE	DESCRIPTION
1	1477K-04....	LOCK REPAIR KIT
2	1477K-01LTD	EXTRA LONG SLIDES (2) 45KG TOP DRAW
3	1477K-01L	EXTRA LONG SLIDES (2) 1 DAAT 45KG
4	1477K-01LBD	EXTRA LONG SLIDES 1 DAAT (2) 45KG
5	1477K-01A	PAIR OF ALU PILLARS 131MM 2SL (INSIDE)
6	1477K-ACTP	COMPOSITE TOP MIDDLE PART
	1477K-ACTD	MDF TOP
	1477K-ACTSS	STAINLESS STEEL TOP
	1477K-ACTW	WOODEN TOP
7	1477K-DR1-B	BUMPER FOR DRAWERS 1 SLOT (2 UNITS)
8	1477K-DR2-B	BUMPER FOR DRAWERS 2 SLOT (2 UNITS)
9	1487K-FR-BB	BACKSIDE BUMPER (2 UNITS)



1487K4 (E77)

Revision: 01



SNA Europe does not cover the causes over negligence in tool use and/or repair, inadequate care, or abnormal usage conditions. Follow the instructions for proper use, safety, maintenance and servicing given by SNA Europe

16062025